## Approved For Release 2002/06/13 PEREP68B00724R000200240007-7

IDEA-0252-69 Copy of 9

14 March 1969

	MEMORANDUM FOR: Deputy for Operations, OSA Deputy for Research and Developm	ent, OSA	
	SUBJECT: 6 March 196 Overhaul of Delta III S/N 5 Came		25X1
25X1	REFERENCE: Telecon , Headquar Delta III Camera Reservative.	,	25X1
25X1	1. Recently Delta III Camera S/N 2 was returned as no longer required at that Operational problems were encountered at ho could not be duplicated by flights. (Attable1 Delta S/N 2 is now O.R. at	location. wever 2 chment 1) 2	25X1 25X1
25X1	2. Delta III Camera S/N 3, at was s for S/N 5 at S/N 5 has considerably more time than the other cameras as is indicated in pedata (Attachment 1).	wapped operational	25X1
25X1 25X1	3. S/N 2 and S/N 5 will be maintained at O.R. condition; however, due to operational time it is anticipated that this camera will be margin until such time as camera receives an IRAN. In r telecon indicated IRAN of S/N 5 would co pending condition of camera fr condition to worst. Request your comments:	on S/N 5 al O.R. eference st from	25X1
	A. Delta III S/N 5 should receive IRAN  B. Delta III S/N 5 be maintained as "on	the	
	shelf spare" and used as backup in operation condition as is.		05V4
			25X1
25X1	Deputy for Mater	iel, OSA	

Approved For Release 2002/06/13 : CIA-RDP68B00724R000200240007-7

downgrading and

## Approved For Release 2002/06/13: CIA-RDP68B00724R000200240007-7

SECRET

IDEA-0252-69 Page 2

Attachment: a/s

25X1

MD/M/OSA/ (10 March 1969) Distribution:

#1 - D/O/OSA w/att

#2 - D/R&D/OSA w/att

#3 - DD/SA w/att #4 - D/M/OSA w/att

#5 - MD/M/OSA wo/att

#6 - CMD/OSA w/att

#7 - B&FD/COMPT/OSA w/att

#8 - MD/M/OSA (Chrono) wo/att #9 - RB/OSA wo/att